

CASE STUDY: DIESEL GENERATOR

LOCATION: OFFSHORE PLATFORMS

MARKET: OFFSHORE

REQUIREMENT:

A system was required for the protection of internal surfaces, electrics and electrical boxes, moving parts and external areas.

SOLUTION:

- CCI 450 was sprayed onto all exposed electrics
- CCI V100 Tape was used to treat all the electrical boxes
- CCI 300M was added to the lubricating system and misted into the injectors
- CCI Powder was blown into the main cavities
- CCI 350 was applied to all moving parts
- CCI 400 was sprayed on to all external surfaces

